

UREA GRANULAR

Is used in the industry as raw material for manufacture of pitches, glue, etc., and also in agriculture as mineral nitric fertilizer.

QUALITY PARAMETERS

PARAMETRES DESCRIPTION		NORMS	ACTUAL PARAMETER
1	Nitrogen mass fraction as dry substance % not less than	46,2	
2	Biuret mass fraction, % not more than	1,4	
3	Water mass fraction acc. to fisher method % not more than	0,5	
4	Granules mass fraction 2-5mm, % not less than	65	
5	Granules mass fraction <1 mm, % not more than	0,5	
6	Granules mass fraction residue on the sieve 6mm, %	Absence	
7	Statistic strength, % not less than	2	
8	Conditioning admixture, %	0,3	
9	Appearance, color	White or slightly a colored granules	